
**Matrox Imaging Library (MIL) 10 Update 20
Release Notes (Matrox Intellicam)
April 2017
(c) Copyright Matrox Electronic Systems Ltd., 1992-2016.**

This document outlines what is new with Matrox Intellicam and explains the current limitations and particularities.

Contents

- [1. Matrox Intellicam](#)
 - [1.1 Summary of bug fixes](#)
-

1. Matrox Intellicam

1.1 Summary of bug fixes

- Having insufficient non-paged memory did not always get reported properly and led to incorrect video acquisition (typically black video or a frame rate of 0 fps). Matrox Intellicam now reports an appropriate error message telling users to increase non-paged memory using Matrox MilConfig utility.
- Fixed inconsistencies in the menus associated with Matrox GigE Vision, Matrox USB3 Vision, or Matrox Clarity UHD systems.